

	GOVERNMENT OF NEWFOUNDLAND AND LABRADOR Department of Transportation and Infrastructure	BRIDGE INSPECTION REPORT B11122015-2	
Date: 10/25/2015	Inspected By: Rodger Hussey	Category: Eng. - Engineering	
BRIDGE INFORMATION			
Site:	1-385 - KENMOUNT ROAD NORTH OVERPASS		
Route:	3	Overall Length:	58.1 m
Year Built:	2012	Est: No	Overall Width: 10.75 m
Year Last Rehab.:		Est: No	Roadway Width: 9.8 m
Region:	AVALON PENINSULA		Sidewalk Width: 0 m
Jurisdiction:	Provincial	Clearance to R.D. or N.W.L.:	0 m
Type of Structure:	05 - Pre-stressed Concrete Slab		Max Depth of N.W.L.: 0 m
Purpose of Structure:	01 - Highway Grade Separation		Spans:
Type of Handrail:	05 - Concrete Barrier		<u>Span No.:</u> <u>Length</u> <u>Span No.:</u> <u>Length</u>
Roadway Surface:	02 - Asphalt	1	15.6 4 0
Alignment Vertical:	01 - Good	2	26 5 0
Alignment Horizontal:	01 - Good	3	15.6 6 0
Restrictions:	No		
BRIDGE PHOTOS			
SUBSTRUCTURE			
Condition:	G - Good	Bearings:	G - Good
		Bearing Seat:	G - Good
Comments:			
SUPERSTRUCTURE			
Condition:	G - Good	Expansion Joints:	G - Good
Comments:			
DECK			
Condition:	G - Good	Curbs:	I - Inapplicable
Hand Rail:	G - Good	Roadway Condition:	I - Inapplicable
Approach Rail:	G - Good		
Comments:	Jersey barrier handrails; Deck not paved; Bridge not in active use.		
HYDROLOGY			
Water Velocity:	0 m/s	Ice Problem:	NA - Not Applicable
Water Depth:	0 m	Scour Problem:	NA - Not Applicable
Waterway:	03 - Not Applicable	Debris Problem:	NA - Not Applicable
Comments:			

REPLACEMENT/REHABILITATION			
Next Rehab. Date:	2015	Replacement Year:	2015
Antic. Rehab. Cost:	\$0	Replacement Cost:	\$0
Recommendations:			
OBSERVATIONS			
Overall Condition:	G - Good	Requires Further Inspection:	No
Additional Observations: Recently constructed; Standing water on bridge deck.			
LEGEND:			
Condition Definitions:		Problem Definitions:	
1 - *Good - [discontinued code].	F2 - Fair.	C - Unsafe (Closed to Public).	N - No Problem.
2 - *Fair - [discontinued code].	F1 - Fair.	U - Uninspectable.	P - Possible Problem.
3 - *Poor - [discontinued code].	P3 - Poor.	I - Inapplicable.	K - Known Problem.
4 - *Unsafe - [discontinued code].	P1 - Poor.		NA - Not Applicable.
G - Good.	P - Poor.		Category Definitions:
			Maint. - Maintenance.
			Eng. - Engineering.
			Office - Bridge Office.
PHOTO GUIDELINES:			
Inspection Photos:			
Please provide photos using guidelines below:			
<ul style="list-style-type: none"> ● Any item which inspector feels should be documented by photograph ● All items noted above as being P3, P1, P, or C ● Any evidence of known ice, scour, debris, waterway problems 			
INSPECTION PHOTOS			

Department of Transportation and Infrastructure, Government of Newfoundland and Labrador 2021.